Tech Connection



November 2016

For Professional Automotive Technicians

ANCO Contour Wiper Blades When you buy 10 or more. C15UB C16UB TANEO. C170E C17UB C18OF C18UB C19UB A beam blade for all seasons! C20OE Exclusive, advanced rubber compound C20UB provides a consistent streak-free wipe C21UB C220E Unique spoiler provides superior blade-C22UB to-windshield contact C240E C24UB Quick and easy wiper blade replacement C260E C26UB or OE-style and Universal fit C280E C28UR

Cabinet with Mini-Light Assortment

\$185⁹⁹

Contains 146 bulbs in a heavy-duty cabinet with tip-out drawers.





Contains:

- Mini-lamps: 10 each of 194, 3157, 1157, 1156, 3057, 921, 3157NA, 7443, 912, 168, 194NA, 3156, 2057
- Driving lamps: 3 each of 1255H11 and 1255H7
- Long Life mini-lamps: 10 each of 4157LL



Beck/Arnley Premium Transmission Fluids

Part #	Туре	Price
252-2001	ATF-HP & MATIC J	6.29
252-2002	ATF-TYPE T-4	5.39
252-2003	ATF-SPIII	6.29
252-2004	ATF-Z1	6.99
252-2005	ATF-M5	7.09
252-2006	AFT - WS	7.89
252-3000	CVT - NS2	14.89

All transmission fluids are sold in quarts. www.beckfluids.com



PS Fluid for Honda & Acura

\$359

12oz #252-0020



Effective Nov. 1-30, 2016

All products may not be available in all locations. We reserve the right to limit quantities and substitute equal/like items for out-of-stock or discontinued merchandise. Not responsible for typographical errors. ©2016 IEH Auto Parts LLC. All rights

Auto Plus and the Auto Plus Expertise at Every Turn logo are service marks of IEH Auto Parts LLC.

Your local Auto Plus store.





QD[®] Electronic Cleaner

\$545

each #05103





Red "N" Tacky Multi-Purpose Grease

\$3⁷⁹

#10005-60



High Strength Red Threadlocker

\$399

each #27100





Fast Orange Hand Cleaner

\$299

each 15oz bottle #25122 (pumice) #23122 (smooth)



JB Weld

\$359

#8265S

Spray Nine

\$499

per quart #26832



NEW PRODUCT UPDATE FROM DORMAN

Nissan Electronic Steering Column Lock Actuator - Available from Auto Plus!

Dorman Products has recently designed an OE Fix solution to the Nissan steering column lock failure problem. Several Nissan vehicles, including the popular Altima and Maxima, suffer from an extremely high rate of steering column lock actuator failures. The original unit typically fails due to worn gear teeth, which eventually leads to a locked steering wheel and the inability to start the vehicle.

Dorman's OE Fix replacement part features:


- A stronger compound gear material for added durability
- Updated software to adjust gear speed minimizing gear teeth wear
- Exclusive smart remote programming tool included to eliminate a costly trip to the dealer



Gates 'Don't Forget the Hoses' Installer Promotion

www.GatesRebates.com Register here for all Gates promotions!

Receive a YETI tumbler when you install Gates hoses. See flyer or website for complete details. Sept 1-Nov 30, 2016



Radiator and water pump replacement spikes around 9 years. Radiator hose failure spikes around 11 years. Providing a customer with a brand new water pump or radiator, but not new radiator hoses is like setting a ticking time bomb for a comeback. Surprisingly, repair records show that 90% of the time, the old hoses are put back on with the new radiator or water pump. SOLUTION:

Avoid customer comebacks by replacing all worn system components with every cooling system repair.





